

Tornador Black - Ersatzteilpreise

| | | GH | HV |
|----|-------------|-----------------------------|-------|
| 1 | SPZ010001 | Housing | 16,78 |
| 2 | SPZ010030 | Gasket(10x16.5x2) | 22,14 |
| 3 | SPZ010025 | Screw | 0,55 |
| 4 | SPZ020001 | Hose | 1,40 |
| 11 | SPZ020008 | Nozzle | 1,85 |
| 12 | SPZ010007A | Trigger Stud | 23,35 |
| 13 | SPZ010008A | Trigger Screw | 30,82 |
| 14 | SPZ010009 | Trigger | 5,63 |
| 15 | SPZ010011 | Screw | 7,43 |
| 17 | SPZ010028 | O-Ring(9x2) | 1,05 |
| 18 | SPZ010027 | O-Ring(3.5x1.5) | 1,39 |
| 19 | SPZ010012 | Bushing | 2,75 |
| 20 | SPZ010013 | Gasket | 3,63 |
| 21 | SPZ020009A | Inner Tube Ass'y | 1,75 |
| 22 | SPZ010017 | Air Reverse Switch Ass'y | 2,31 |
| 23 | SPZ010018 | Screw | 0,20 |
| 24 | SPZ010019 | Cap(with 2 hole) | 0,10 |
| 24 | SPZ010019-1 | Cap(closed) | 0,13 |
| 25 | SPZ010021 | Nut | 1,05 |
| 26 | SPZ010020 | Gasket | 1,39 |
| 27 | SPZ010022 | Tube Ass'y(inkl.part.no.28) | 0,20 |
| 29 | SPZ010023 | Cup | 3,13 |
| 30 | SPZ010014 | Valve Stem | 9,65 |
| 31 | SPZ010015 | Spring | 2,49 |
| 32 | SPZ010026 | O-Ring(4.47x1.78) | 1,88 |
| 33 | SPZ010010 | Screw | 2,48 |
| 34 | SPZ010024A | Air Inlet(1/4"PF) | 1,40 |
| AK | SPZ0200AK | Rotate set | 1,60 |
| | | | 2,11 |
| | | | 6,88 |
| | | | 9,08 |
| | | | 12,38 |
| | | | 2,90 |
| | | | 0,40 |
| | | | 0,20 |
| | | | 1,39 |
| | | | 3,30 |
| | | | 44,79 |
| | | | 59,12 |

